

cron

16. Mount Electronics

Written By: Paul Cronje




Step 1 — Parts Required: 1




- Electronics MDF board
- CNC Electronics Module
- Relay Module
- Nuts & Bolts (see next step)

Step 2 — Parts Required: 2




- M3 Lock Nut (8 Pcs)
- M3x10 Cap Screw (8 Pcs)


Step 3 — Tools Required



- 2.5mm Allen Key
- Sharp nose pliers

Step 4 — Mount the controller board






- Remove the Arduino Uno from the CNC shield
- Mount the Arduino Uno with the M3x10 Cap Screws (4 Pcs) and the M3 Lock Nuts (4 Pcs) in the holes shown in red in the picture
- Do not over tighten the screws, just make sure the board is secure
- Assemble the CNC shield back onto the Arduino Uno. Make sure all the pins goes back into the headers on the Arduino.

Guide ID: 16 - Draft: 2021-01-19

Step 5 — Mount Relay

16. Mount Electronics





- If you are instaling a laser assembly aswell you will need to follow the following link and do not fasten this relay.
 O3. Prepare the new relay assembly
- Mount the relay with the M3x10 Cap Screws (4 Pcs) and the M3 Lock Nuts (4 Pcs) in the holes shown in green in the picture
- Do not over tighten the screws, just make sure the relay is secure